






Offshore Decommissioning: **WASTE DUTY OF CARE**

WASTE PRODUCERS: have a responsibility to take all reasonable steps to ensure that the waste is managed correctly throughout its complete journey to disposal or recovery

YOU must take all reasonable steps to:

- ➔  Accurately describe and classify the waste
- ➔  Check authorisation of the next waste holder
- ➔  Ask the next waste holder where they are taking it
- ➔  Carry out detailed checks if you suspect non-compliance
- ➔  Prevent the escape of waste from your control

FAILURE TO COMPLY
WITH THE DUTY OF CARE
REQUIREMENTS IS A CRIMINAL
OFFENCE AND COULD LEAD TO
PROSECUTION



D3 CONSULTING provides **WASTE ASSURANCE**
support for the complete decommissioning cycle

